

G 348598 IP

# Fault Report

Customer Name: IP	Date:
Customer Reference: 348598	Fitter:
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: SHUTTER 5 FRAME AT BOTTOM DAMAGED. SHOULD BE LR OPENING. COVER STRIPS FOR MIDDLE(3) SHUTTER. 2 @ 5x35x1375 SHUTTER 2 PACK BOTTOM HINGE, SCREW FRAME CLOSER TO CILL.	
Action to correct: 3 HRS REQUIRED TO FIX.	
Problem fixed on site: Yes/No	
Further action required:	