

S 351524
Wilson | R

Fault Report

| | |
|---|----------------------------|
| Customer Name: Wilson | Date: 13/12/21 |
| Customer Reference: 351524 | Fitter: CRAM |
| Salesperson: Adam | Salesperson called: Yes/No |
| Blind Type and number: | |
| Fault Description: roller no 2 should be blackout. | |
| Action to correct: replace roller | |
| Problem fixed on site: Yes/No | |
| Further action required: | |