

S 351309
Dixon IR

Fault Report

Customer Name:

Dixon

Date:

21/12/21

Customer Reference:

351309

Fitter:

CRAIG M

Salesperson:

Salesperson called: Yes/No

Blind Type and number:

Fault Description:

roman chain needed needs
to be 1040 long

Action to correct:

replace roman chain

Problem fixed on site: Yes/No

Further action required: