

G 346316  
Shaw IR

# Fault Report

Customer Name

Shaw

Date

11/1/21

Customer Reference

346316

Order

CR1716 M

Salesperson


Salesperson called: Yes/No

Blind Type and number

shutter

Fault Description:

replace cover strip (damaged)  
LH side of bay window at bottom



Action to correct:

replace cover strip.

Problem fixed on site. Yes/No

Further action required: