

G 351951
Rogerson/R

Fault Report

Customer Name: Rogerson	Date: 21/3/22
Customer Reference: 351951	Fitter: CRAIG M.
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: need to TAKE OUT 2X control rods both at 800mm. (missing)	
Action to correct: TAKE 2X control rods at 800mm To suit p/fit (V)	
Problem fixed on site: Yes/No	
Further action required: Ordered.	