

S 351885


Dickens/R1

Fault Report

Customer Name: Dickens	Date: 07.02.22
Customer Reference: 351885	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: <input checked="" type="radio"/> Yes / <input type="radio"/> No
Blind Type and number: Tensioned Pleated, blind 1 (Snug)	
Fault Description: Blind exceeds the recommended width causing it to bow.	
Action to correct: N/A	

Problem fixed on site: Yes No

Further action required: Customer requires 3nr blinds the same as original, sizes below



A, B, C = 570mm exact
D = 1450mm " "
B = 575mm " "