

G 349376

Bowman/R

Fault Report

Customer Name: Bowman	Date: 21/2/22
Customer Reference: 349376	Fitter: CRAN M
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: replace rollers LH bed roller and middle bay roller both frayed as not pulling up properly.	
Action to correct: replace rollers	
Problem fixed on site: Yes/No	
Further action required: Re-Ordered Blind (1) B (4)	