

G 352281
Hedley IR

Fault Report

Customer Name: Hedley	Date: 05.04.22 05.04.22																														
Customer Reference: 352281	Fitter: Scott Johnson																														
Salesperson: Dave	Salesperson called: Yes <input checked="" type="checkbox"/> No																														
Blind Type and number: Blinds 1 to 9 Verticals																															
Fault Description: Blinds should have been ward control, Customer has decided to go with Cord Control see below for positions.																															
Action to correct:	<table border="1"> <thead> <tr> <th>Blind</th> <th>Control</th> <th>Bunch</th> </tr> </thead> <tbody> <tr><td>1</td><td>RH</td><td>RH</td></tr> <tr><td>2</td><td>RH</td><td>RH</td></tr> <tr><td>3</td><td>LH</td><td>LH</td></tr> <tr><td>4</td><td>LH</td><td>LH</td></tr> <tr><td>5</td><td>RH</td><td>Split</td></tr> <tr><td>6</td><td>RH</td><td>RH</td></tr> <tr><td>7</td><td>RH</td><td>RH</td></tr> <tr><td>8</td><td>LH</td><td>LH</td></tr> <tr><td>9</td><td>LH</td><td>LH</td></tr> </tbody> </table>	Blind	Control	Bunch	1	RH	RH	2	RH	RH	3	LH	LH	4	LH	LH	5	RH	Split	6	RH	RH	7	RH	RH	8	LH	LH	9	LH	LH
Blind	Control	Bunch																													
1	RH	RH																													
2	RH	RH																													
3	LH	LH																													
4	LH	LH																													
5	RH	Split																													
6	RH	RH																													
7	RH	RH																													
8	LH	LH																													
9	LH	LH																													
Problem fixed on site: Yes/No																															
Further action required: new headrails need ordered and delivered on Tuesday 12 th April.																															