

Fault Report

Customer Name: Cummins	Date: 23.05.22
Customer Reference: 352494	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes (No)
Blind Type and number: Blind 2 (Kitchen 1) Motorised Roller	
Fault Description: receiver wire Caught in roller and Snapped.	
Action to correct: please check with Josh, I believe it needs a replacement Motor	
Problem fixed on site: Yes (No)	
Further action required: order new Motor and replace.	