

Fault Report

Customer Name: Harrison	Date: 08.07.22
Customer Reference: 352559	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes/No
Blind Type and number: Blind 2 (Front Bed) Curtain track	
Fault Description: After a discussion with Nicole about the overlap arm which was not delivered, We discovered this is the incorrect track type (the 1080 track doesn't not supply an overlap arm). I need the correct track and an overlap arm to complete this job.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new track and overlap arm.	