


G 352452  
Barnes. R

# Fault Report

Customer Name: Barnes	Date: 352452
Customer Reference: 11.05.22	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes (No)
Blind Type and number: Blind 2 (Sun Room 2) P/fit plecter	
Fault Description: Left leg on blind doesn't have holes for brackets, new leg needs sent.	
Action to correct: New leg with holes needs sent (anthracite)	
X = leg that's needed.	
	
Problem fixed on site: Yes (No)	
Further action required: N/A	
Glass Size - 785 x 1830	

Anthracite Frame