


G352574

Fault Report

Customer Name: Oladapo	Date: 20/06/22
Customer Reference: 352574	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes (No)
Blind Type and number: Blind 1 (lounge) Roller	
Fault Description: roller was detached at the Join (top half still up, Bottom half in unit) Customer was asked for a Stronger band if remade the same	
Action to correct:	
	
Problem fixed on site: Yes (No)	
Further action required: order and replace blind.	