

S 350870

Stevn/R.

# Fault Report

Customer Name: Stevn	Date: 23/6/22
Customer Reference: 350870	Filter: CRAIG in
Salesperson: Shaun	Salesperson called: Yes/No
Blind Type and number: PLATE NO'S 9+10	
Fault Description: Remove plate no's 9+10 as controls are wrong no 9 should be LH no 10 should be RH.	
Action to correct: Remove 2x plate vens	
Problem fixed on site: Yes/No	
Further action required: Inputted correctly. Looks like a factory error.	