

G 351805
Lamb. R

Fault Report

Customer Name: lamb	Date: 15/7/22
Customer Reference: 351805	Fitter: CRAG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: venetian	
Fault Description: replace ven (controls wrong) controls should be (LL)	
Action to correct: replace venetian controls wrong should be (LL)	
Problem fixed on site: Yes/No	
Further action required:	
Office Error	