

S351294

Fault Report

Customer Name: Jewitt	Date: 12.10.22
Customer Reference: 351294	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical, Landing	
Fault Description: Slates should be 5 inch not 3 ½ inch.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new slats and head rail, please call customer and let them know a new installation date.	
Incorrect blind installed and paid for. Straight swap on service call	