

S 354085

Fault Report

Customer Name: Peart	Date: 21.10.22
Customer Reference: 354085	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: All venetian 50mm metal	
Fault Description: Control wands have all snapped and are now all different sizes.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new wands for the six blinds so each room has matching wands. 3x FH 2300 3x FH 2500.	