

G353239

DICKSON / R

Fault Report

Customer Name: Dickson	Date: 06.02.23
Customer Reference: 353239	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised roller (bi-fold 2) Blind 6	
Fault Description: Roller incorrect on tube, causing it to run out more noticeable as it is in a line of 4 on a bi-fold door.	
Action to correct: Tried to adjust but was unsuccessful	
Problem fixed on site: No	
Further action required: Remake roller only and I will install original motor and cassette.	