

S354186

COOPER

# Fault Report

Customer Name: COOPER 354186	Date: 16-2-23
Customer Reference:	Fitter: CRAIG / GRAEME
Salesperson: SHAWN	Salesperson called: Yes/No <input checked="" type="radio"/>
Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: LIV SHUTTER TOO BIG	
Fault Description: SHUTTER IS 3745 WIDE. TOO BIG WITHOUT T POST OR TRACK SYSTEM.	
Action to correct: REMOVE WITH T POSTS AS DISCUSSED WITH CUSTOMER.	
Problem fixed on site: Yes/No	
Further action required:	