

G353878

BURT

Fault Report

Customer Name: Burt	Date: 05.06.23
Customer Reference: 353878	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised roller Bay1	
Fault Description: Motor/Battery not holding charge.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new motor/Battery (Redup ETS 28).	