

S 354538

JOHNSON

Fault Report

Customer Name: Johnson	Date: 07/06/23
Customer Reference: 354538	Fitter: CRAM M
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: re-order L Door panel for R bed shutter has slight paint chip also need light bar with catch plates (same shutter)	
Action to correct: order L door panel for shutter no 2 R bed also need a light bar with catch plates	
Problem fixed on site: Yes/No	
Further action required:	