

G353878

BURT

② Fault Report

Customer Name: Burt	Date: 16.06.23
Customer Reference: 353878	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller (motorised), bay 1	
Fault Description: Incorrect motor sent 1240297A roll up 24 WF RTS Li-iON unit is needed not RU basic 28WF RTS Li-iON II.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new motor, 1240297A roll up 24 WF RTS Li-iON	