

Fault Report

Customer Name: HALL	Date: 12-6-24
Customer Reference: 355095	Fitter: GRAEME
Salesperson: SHAUN	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input checked="" type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: LIV PATIO SIDE	
Fault Description: SHAUN HAS ORDERED AS SPLIT DRAW SHOULD BE LEFT DRAW.	
Action to correct: RAIL TO BE SENT BACK TO CHANGE. MAKE TEMP HEADRAIL IN MEANWHILE.	
Problem fixed on site: Yes/No	
Further action required:	

SHAUN DID NOT

NOTE PAPERWORK

MANUAL TO BE

INSTALLED WHILE

MOTORIZED AMENDED

(IF CUSTOMER CALLS)