

0179998621

355094 / R  
Roper

# Fault Report

Customer Name: Date: James Roper ~~355049~~

Customer Reference: Fitter: OAN

Salesperson: Salesperson called: Yes  No

Blind Type and number:

Roller L + R Beo.

Fault Description:

Blinds have mark on also starting to curling on sides

Action to correct:

Blinds need to be replaced because of mark on fabric.

Problem fixed on site: Yes  No

Further action required:

Would recommend speaking to customer before we re make blinds and change fabric, as I believe the heat is making the blinds start to curl.

Can use moto's that are currently installed would just be 2 new blinds.

355094