

# Fault Report

Customer Name: <a href="#">Harvey</a>	Date: <a href="#">15.02.23</a>
Customer Reference: <a href="#">355107</a>	Fitter: <a href="#">Scott Johnson</a>
Salesperson: <a href="#">Dave</a>	Salesperson called: <a href="#">Yes</a>
Blind Type and number: <a href="#">Roller</a>	
Fault Description: <a href="#">Blind was measured incorrectly due to tiles on revels. Recess width is 877mm, Recess with tiles 864mm. see images, customer would like the blind to be centre of the tiles. Current gaps on tiles are 2mm left 20mm right.</a>	
Action to correct: <a href="#">N/A</a>	
Problem fixed on site: <a href="#">No</a>	
Further action required: <a href="#">I suggest cutting the down the blind by 15mm. Bracket may need moved.</a>	