

C1358332

MASON

Fault Report

FITTER NAME: Scott Johnson	FITTING DATE: 18.11.24
Customer Name: Mason	
Customer Ref: 358332 <i>Service call</i>	
Salesperson: Dave	Salesperson called: <input checked="" type="checkbox"/> Yes/ <input type="checkbox"/> No
Blind Type and number: Wood venetians	
Problem fixed on site: <input checked="" type="checkbox"/> Yes/ <input type="checkbox"/> No	
Fault Description: Measured incorrectly, there is a step in the bay soffit that needs additional timber fitted (by customer) to allow the blinds to be fitted correctly	
Action to Correct:- Customer is going to call in the new year for me to go back out and refit blinds 1 hr needed.	