

G358836
Gibson/R.

② Fault Report

| | |
|--|---|
| Customer Name: Gibson. | Date: 06.08.25. |
| Customer Reference: 358836. | Fitter: Daw. |
| Salesperson: Dave | Salesperson called: Yes/No |
| Order Inputting Error <input type="checkbox"/> | Mismeasure <input type="checkbox"/> |
| Production Error <input type="checkbox"/> | Supplier Error <input type="checkbox"/> |
| Fitting Error <input type="checkbox"/> | |
| Problem fixed on site: Yes/No | |
| Blind Type and number: both shutters. | |
| Fault Description: Shutter tape required for cover strips. | |
| Action to correct: Send some shutter tape down and make follow up app to apply. * all other problems sorted. | |

358836

① Fault Report

| | |
|--|--|
| Customer Name: <u>Gibson.</u> | Date: <u>11.07.25.</u> |
| Customer Reference: <u>358836</u> | Fitter: <u>Dan + Scott.</u> |
| Salesperson: <u>Dave.</u> | Salesperson called: Yes <u>(No)</u> . |
| Order Inputting Error <input type="checkbox"/> | Mismeasure <input type="checkbox"/> |
| Production Error <input type="checkbox"/> | Supplier Error <input checked="" type="checkbox"/> |
| Fitting Error <input type="checkbox"/> | |
| Problem fixed on site: Yes <u>(No)</u> | |
| Blind Type and number: <u>Bed shutter T bar.</u> | |
| Fault Description: <u>dent / chip in T bar number 2.</u> | |
| Action to correct: <u>replace T bar in shutter.</u> <u>& photo added for Supplier.</u> <u>—————</u> | |

Delos/Rs - see fault report ② JA.

