


UK 6849
FLYNN/RS
ON 2697126

Fault Report

Customer Name: FLYNN	Date: 25-7-24
Customer Reference: 6849	Fitter: DAVIS
Salesperson: DAVIS	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: INTU ROLLERS	
Fault Description: BOTH BOTTOM BARS DONT FIT BETWEEN SIDE CHANNELS	
Action to correct: 	
Problem fixed on site: Yes/No	
Further action required: BOTTOM BARS NEED 7mm TAKEN OFF THEM	