

GC 6520

MUNRO/R.

Fault Report

Customer Name: <i>MUNRO</i>	Date: <i>29-8-23</i>
Customer Reference: <i>6520</i>	Fitter: <i>DAMJ</i>
Salesperson: <i>MARK R</i>	Salesperson called: <input checked="" type="checkbox"/> Yes/ <input type="checkbox"/> No
Inputting Error <input checked="" type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: <i>VERTICAL</i>	
Fault Description: <i>SLATS SHOULD HAVE BEEN CHAINED AT BOTTOM</i>	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: <i>NEW SLATS WITH CHAINING</i>	