

GC 6849
FLYNN / R2
ON26971R2
ON26971R3

Fault Report

| | |
|---|----------------------------|
| Customer Name: Flynn | Date: 14/05/24 |
| Customer Reference: 6849 | Fitter: David |
| Salesperson: David | Salesperson called: Yes/No |
| Blind Type and number: Door Right | |
| Fault Description: Material is starting to fray and catch on the pf frame (Emailed pictures in) | |
| Action to correct: | |
| Problem fixed on site: Yes/No | |
| Further action required: New blind required New chain also needed for sunroom 1 blind (plastic breakaway chain at 2100 install height drop 1500. | |

29.05.24

Fabric has been made the wrong way.

Fabric need to be turned opposite way.

(As per david's photos from previous fault report)