

20255
Strachan

Fault Report

Customer Name: Strachan	Date: 20/4/22
Customer Reference: 20255	Fitter: Ross
Salesperson: Lameron	Salesperson called: Yes/No Lameron
Blind Type and number: Roll 1 #	
Fault Description: Blind to Big needs cut down d eyelets inserted	
Action to correct: Insert silver eyelets + cut down blind do 1723 FW.	
Problem fixed on site: Yes/No	
Further action required: Yes.	

*no eyelets added on matrix
*mismeasured *