

Fault Report

Customer Name: 20187	Date:
Customer Reference: Macnamara	Fitter: RB
Salesperson: Martin	Salesperson called: Yes/No
Blind Type and number: VENT	
Fault Description: Rail do BIG . Slot too long .	
Action to correct: needs do 330 EXACT . wide . Slots need do be 1405 recess	
Problem fixed on site: Yes/No	
Further action required:	