

# Fault Report

Customer Name PHILIP	Date; 28/10/24
Customer Reference: 25047	Fitter MC
Salesperson: STUART	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: Vert 2 should be RR not LR cant turn rail around as slats will hit handles & stack would be on the wrong side.	
Action to correct: Remake Rail as RR	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Customer on holiday until 09/11/24.	