

Fault Report

Customer Name GEDDES	Date; 20/12/24
Customer Reference: 25300	Fitter MICHAEL
Salesperson: David	Salesperson called: Yes/ <input checked="" type="radio"/> No
Fault Description: slats should be 1420 recess or 1370 Hem to Hem not 1370 recess	
Action to correct: Remake slats	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required: Yes	