

Fault Report

Customer Name SCOTT	Date; 20/01/25
Customer Reference: 25321	Fitter MICHAEL
Salesperson: STUART	Salesperson called: Yes <input checked="" type="radio"/> No
Fault Description: Blind too tight @ bottom of recess	
Action to correct: make new blind @ 1770 Recess	
Problem fixed on site: Yes <input checked="" type="radio"/> No	
Further action required: Yes	