

# Fault Report

Customer Name IKETCHI.	Date; 20/2/25.
Customer Reference: IKETCHI / 25038	Fitter Various.
Salesperson: STUART	Salesperson called: Yes/No best buds now.
Fault Description: Loosened top string and made to loose to hold up. when correct tension applied its too tight and slats dont close properly.	
Action to correct: MAKE BIGGER DROP 633mm. =	
Problem fixed on site: Yes/No	
Further action required: Re-make, tried <u>every</u> <u>effort</u> to get this one on.	