

# Fault Report

Customer Name CROOK	Date; 29/06/25
Customer Reference: 0541	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/No

## Fault Description:

Rollers should be brown brackets & components (mechanisms)

verts in conserv should have brown extension brackets (slats hitting brkts)

## Action to correct:

supply new components & brackets.

Problem fixed on site: Yes/No

## Further action required:

yes, supply new brackets & refit.