

Fault Report

Customer Name MURRAY	Date; 02/06/25
Customer Reference: 25810	Fitter MICHAEL
Salesperson: LEWIS	Salesperson called: Yes/No <input checked="" type="radio"/>

Fault Description:

only 5mm between plaster board
and steel lentiil cant drill
through

Action to correct: Customer will install
a piece of wood with adhesive
and we will fit onto the wood.

Problem fixed on site: Yes/No

Further action required:

Yes return to fit after
wood is installed