

SB 6010  
MCDONALD /R

# Fault Report

Customer Name: Mcdonald	Date: 13/10/23
Customer Reference: 6010	Fitter: David
Salesperson: David	Salesperson called: Yes/No
Blind Type and number: Intu, venetian, venetian remote	
Fault Description: Wrong remote for the motorised venetian. Intu blinds missing the clear plastic part that goes on the top slat to allow them to turn. Hall venetian made in wrong slats	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required:  New hallway (side window) blind made in 1872 slat. Clear plastic venetian parts for intu blinds. New remote for tilt and turn venetian.	