

SB 7049
WAUGH/R.

Fault Report

SB756121

| | |
|--|---|
| FITTER NAME: Ross | FITTING DATE: 11/12/24 |
| Customer Name: Waugh | |
| Customer Ref: 7049 | |
| Salesperson: Ronnie | Salesperson called: Yes/No <input checked="" type="radio"/> |
| Blind Type and number: Sunwood Ground floor bedroom | |
| Problem fixed on site: Yes/No <input checked="" type="radio"/> | |
| Fault Description blind too tight at bottom New size taken. 1606 x 1265 FH 2020 | |
| Action to Correct:- Remake correct blind | |

Fault Report

BM 751R

| | |
|--|---------------------------------|
| FITTER NAME: DAVID | FITTING DATE: 22-11-2024 |
| Customer Name: WAUGH | |
| Customer Ref: 7049 | |
| Salesperson: RONNIE | Salesperson called: Yes/No |
| Blind Type and number: SUNWOOD (1) BEDROOM | |
| Problem fixed on site: Yes/No | |
| Fault Description BLIND DAMAGED IN SEVERAL SLATS | |
| Action to Correct:- <ul style="list-style-type: none">• REMAKE REQUIRED• COULD STICKY PADS FOR PELMET ALSO BE REQUESTED AS MISSING FROM ONE OF OTHER BLINDS. <p>Wrong blind Remade!</p> | |

1606 x 1265 FH 2020