

Fault Report

Customer Name: Bell	Date: 9/8/22
Customer Reference: 4809	Fitter: Mike
Salesperson: Mark E	Salesperson called: Yes/No
Blind Type and number: Verticals	
Fault Description: Too many controls in the corner - difficult to use and slats don't move fully.	
Action to correct: Supply 2 new white vertical headrails. 1 @ 1540 RH stack with LH controls 1 @ 1570 LH stack with RH controls Also supply continuous chains for rollers + safety clips.	
Problem fixed on site: Yes/No	
Further action required:	