

Fault Report

Customer Name: FLYNN	Date: 30-9
Customer Reference: 6748	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: 1	
Fault Description: TILT ROD CLIP SWAPPED ON BLIND	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: NEW REPLACEMENT RE MECHANISM NEEDED	