

Rain 5806
Gibson/R.

Fault Report

Customer Name: GIBSON	Date: 09-12-22
Customer Reference: 5806	Fitter: CARM
Salesperson: GREAME	Salesperson called: Yes/No
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input checked="" type="checkbox"/>	Supplier Error <input type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: CURTAINS	
Fault Description: CURTAINS TOO LONG NO HOOKS	
Action to correct: SHORTEN CURTAINS, 32 HOOKS ON EACH CURTIAN MAKE CURTAIN TO ORIGINAL SIZE AS PER NICOLE.	
Problem fixed on site: Yes/No	
Further action required: 32 Hooks each side Opening 4770 drop - 1965	