

ED 4636  
OSOWSKA

# Fault Report

Customer Name: OSOWSKA	Date: 7-6-23
Customer Reference: 4636	Fitter: DAVID
Salesperson: DAVID	Salesperson called: Yes/No
Blind Type and number: CURTAIN	
Fault Description: Been made non B/O	
Action to correct:	
Problem fixed on site: Yes/No	
Further action required: B/O Lining To Be Put ON	