

RAIN 7763

FRASER/R.

Fault Report

Customer Name: <u>Fraser</u>	Date: <u>9/NOV/23</u>
Customer Reference: <u>7763</u>	Fitter: <u>Dylan</u>
Salesperson: <u>Gary</u>	Salesperson called: Yes/ <input checked="" type="radio"/> No
Blind Type and number: <u>Venetian</u>	
Fault Description: <u>Tilting wand was requested to be on right hand side, next to lifting cable, but the tilting wand was on left side.</u>	
Action to correct: <u>Tilting wand to be positioned on right side.</u>	
Problem fixed on site: Yes/ <input checked="" type="radio"/> No	
Further action required:	