S351055

Fault Report

Customer Name: Clark	Date:
Customer Reference: 351 055	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTERS	
Fault Description: Cover strip missing from landing shutter also replace door panel in bathroom as damaged (sent photos to Graham)	
Action to correct: replace bathroom door panel (damaged) and order cover strip for landing missing	
Problem fixed on site: Yes/No	
Further action required: —	