G355575
HENDERSON /K

Fault Report

Customer Name: Date: Henderson 12-6-24
Customer Reference: Fitter: 355575.

Salesperson: DAVE Salesperson called: Yes/No

Blind Type and number: L.H front bed ~~left~~ right door

Fault Description:

Slats not working on shuttee.

Action to correct:

re order door.

Problem fixed on site: Yes/No
Further action required:

Shutter door to be replaced slats
not opperating correctly
L/H front bed – right door.

photo + video added for refrence.