PAUL 07595 068124

ABC0425

ABERDEEN
BLIND COMPANY
ESTABLISHED 1952

32 Esslemont Avenue
Aberdeen
AB25 1SP
Tel: 01224 637609
sales@aberdeen-blinds.co.uk

Customer's Name: CARDEN PROJECTS

Address: SLB
BADEN TON AVE
BADEN TON INS EST

Post Code: AB12 4YB

DATE MEASURED/ORDERED
30/ 01 /26

Measured By:
SN

Special Instructions

AND IN BOTH ROOM + RECESSION
PUT BLINDS CLOSE AS POSSIBLE
TO METAL WINDOW FRAMES

LEGION - ONLY CO-ORDS GIVEN
TRANSFER - ON MATRIX

RECESS / TOP RIM / FROM RECESS RIM

Room	Width	Drop	Slat Size	Colour	Control LH or RH	Fitting Height	Price
TOP (65)	2978	1150	Plan	Pacma	L	2400	~~181~~
	1975				R		~~129~~
	2945				R		~~181~~
	2938				R		~~181~~
	2940				L		~~181~~
	1955				R		~~129~~
FIRST SECOND	2987				L		~~181~~
	1975				R		~~129~~
	2940				R		~~181~~
	2955				R		~~181~~
	2965				L		~~181~~
	1998				R		~~129~~
	2952				L		~~181~~
	1993				R		~~129~~
	1922				L		~~129~~
	2875				R		~~181~~
	853				L		~~21~~
	1828				R		~~129~~
	1940				L		~~129~~
	2020				R		~~136~~
	2895			Brown B/O	L		~~207~~
	841				R		~~21~~
	945				R		~~21~~
40	1635	2020	x	FIT AS CLOSE TO	L		~~207~~
45	2424		x	WINDOW AS POSS	L		~~257~~
45	2680		x	ON LONG WINDOW	R		~~274~~

(6) (982) (20) (31) (P10)

TOTAL PRICE 6970 + VAT

SHOP OPEN Mon-Fri 8 - 5

VAT Reg. No. 265 3431 64

Registered No.: 130460

Au Tonkin
Au Recess
Au 2500 RH

Fault Report

Customer Name: CARDEN PROJECTS	Date: 18/03/26
Customer Reference: ABC 425	Fitter: AMO
Salesperson: SN	Salesperson called: Yes/No
Order Inputting Error ☐	Mismeasure ☒
Production Error ☐	Supplier Error ☐
Fitting Error ☐	
Problem fixed on site: Yes/No	
Blind Type and number: ROLLER #2	
Fault Description: TOO BIG	
Action to correct: CUT IT 10mm.	