S 345768
Armstrong IR.

Fault Report

Customer Name: ARMSTRONG	Date: 20/12/21
Customer Reference: 345768	Fitter: SCOTT
Salesperson: SHAUN	Salesperson called: (Yes)/No
Blind Type and number: SHERWOOD VENETIAN x 1	
Fault Description: ~~BLIND FITTED WRONG POSITION TOO WIDE~~ BLIND IS TOO WIDE - MISMEASURE	
Action to correct: SUPPLY NEW BLIND	
Problem fixed on site: Yes/(No)	
Further action required: REFIT BLIND + ONE ON SITE USING F/FIX EXT (ADJUSTABLE) BKTS - FIX TO FRAME AND CUT PELMET ON FRONT BLIND AND MOVE SIDE BLIND TO (R) TO CLOSE GAP	

342 1608

Rainbow Blinds

WOOD VENETIAN BLINDS

Order Form

Rainbow Blinds & Interiors
61 Canyon Road
Excelsior Park
Wishaw
ML2 0EG
T: 01698 351 888
F: 01698 351 999
sales@rainbow-blinds.com

Date: 20-12-21	Telephone:
Retailer: BAILEYS	Email:
Address: [illegible]	Signature:
Date Required:	Purchase Reference No: 345768 ARMSTRONG

Special Instructions: SUPPLY 5 x EXT FACE FIX BKTS (ADJUSTABLE)

	BLIND SIZE									CONTROLS			BRACKETS	PELMET		ORDER		
	Window	Slat Width 35mm (✓)	Slat Width 35mm (✓)	Slat Width 50mm (✓)	Width (mm)	Drop (mm)	Recess or Exact	Child Safety Installation Height (mm)	Length of Control (mm)	Slat Range and Colour	Operation STD (✓)	Operation LHS (✓)	Operation RHS (✓)	BOX (✓)	Width (mm)	Return (mm)	Price (£)	Qty	TOTAL COST (£)
1	PORCH			✓	1680	1290	I/R	2700		SHERWOOD SILK WHITE			✓					1	
2																			
3																			
4																			
5																			
6																			
7																			
8																			

NOTE: UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS RECESS

All blinds supplied by Rainbow Blinds & Interiors are fitted with an approved Child Safety Device

Customer has been advised on (✓):

- [ ] The Child Safety Regulations EN13120 and the use of child safety devices
- [ ] Minimum distances applying to operating cords

Issue June 2016