G 349411
Tando IR2.

Fault Report

Customer Name: Tando	Date: 7/3/22
Customer Reference:	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number:	
Fault Description: remake pelmet at 2430mm was too short.	
Action to correct: remake pelmet at 2430mm NOT PAID	
Problem fixed on site: Yes/No	
Further action required:	