G 352485
Murray. R

Fault Report

Customer Name: murray	Date: 14/7/22
Customer Reference: 352485	Fitter: CRAIG M
Salesperson:	Salesperson called: Yes/No
Blind Type and number: SHUTTER.	
Fault Description: replace panels on shutter. Customer wanted silent tilt and also a break on tilt at 880mm.	
Action to correct: replace panels on shutter.	
Problem fixed on site: Yes/No	
Further action required: *New Panels Ordered (19/07)*	